

APPENDIX F PHOTOGRAPHIC RECORD

PHOTOGRAPHIC LOG

Photo no.	Date:
1	30/01/25

Description:

Main access gate, hardstanding, AST and northern shed.

View: north-west



Photo No.	Date:
2	30/01/25

Description:

Paint tins, some labelled flammable and gas cylinder within southern building.

View: east



Photo No. 3	Date: 30/01/25	
Description: Evidence of previous site investigation (inc. rock cores, liners and boxes) and damaged roof within southern building. View: south		

Photo No. 4	Date: 30/01/25	
Description: Spoil heap located north-east of hardstanding and sheds. View: north-east		

Photo No. 5	Date: 30/01/25
Description: COSHH warning sign on northern shed. View: north	


--

Photo No. 6	Date: 30/01/25	
Description: Site of removed electrical substation beside electric pylon, north of the northern shed. View: east		

Photo No. 7	Date: 30/01/25	
Description: Electrical infrastructure within previous electrical substation building. View: west		

Photo No. 8	Date: 30/01/25	
Description: AST by northern shed. View: south-west		

Photo No. 9	Date: 30/01/25	
Description: Main quarried area south-east of sheds. View: south		

Photo No. 10	Date: 30/01/25	
Description: Protruding pipe beside concrete structure with brackets. Potential second previous AST. View: south-west		

Photo No. 11	Date: 30/01/25	
Description: Largest settling pond. Client rep stated approximately 3-4 m of silt. View: north		

Photo No. 12	Date: 30/01/25	
Description: North-eastern quarried area. View: east		

Photo No. 13	Date: 30/01/25	
Description: Metal structure dumped north east of the settling ponds. View: north-west		

Photo No. 14	Date: 30/01/25	
Description: Track toward central east of the southern sector. View: east		

Photo No. 15	Date: 30/01/25	
Description: Less defined muddy track down eastern boundary within southern sector. View: south-east		

Photo No. 16	Date: 30/01/25	
Description: Main quarried area and vegetation. View: north-west		

Photo No. 17	Date: 30/01/25	
Description: View toward southern boundary and southern extent of main quarried area with pond. View: south		

Photo No. 18	Date: 30/01/25	
Description: Northern view through quarried area. View: north		

Photo No. 19	Date: 30/01/25	
Description: Southern extent of main quarried area and pond. Southern boundary. View: south-west		

Photo No. 20	Date: 30/01/25	
Description: Ponds located immediately west of site boundary. View: west		

Photo No. 21	Date: 30/01/25	
Description: Gate from bridleway into northern sector. View: north		

Photo No. 22	Date: 30/01/25	
Description: Footpath into northern sector. View: north		

Photo No. 23	Date: 30/01/25	
Description: Northern sector vegetation comprising small trees, brambles, bracken and gorse. View: south		

Photo No. 24	Date: 30/01/25	
Description: Largest northern sector pond. View: east		


Photo No. 25	Date: 30/01/25	
Description: View north through the northern sector. View: north		

Photo No. 26	Date: 30/01/25	
Description: Iron ochre leaching from below largest northern sector pond. View: south-east		

Photo No. 27	Date: 30/01/25	
Description: Track into northern sector. View: south		

Photo No. 28	Date: 30/01/25	
Description: General overview of the presumed location of the eastern shaft within woodland. View: east		

Photo No. 29	Date: 30/01/25	
Description: Presumed location of eastern shaft comprising a hollow with fly tipped waste. View: north		

Photo No. 30	Date: 30/01/25	
Description: Bridleway separating the northern and southern sectors. View: east.		